
Palletizing Computers



Begin by placing four computer towers on each corner of the pallet. Be sure that these towers are placed flat on the pallet

Fill in the narrow spaces by placing computer towers upright between the towers in the corners.



Continue stacking the computer towers. Stack the towers flat on the corners and upright within the gaps.

Stop when the towers are between waist and chest high.



80-gauge shrink wrap works well for wrapping computer towers. Give the material a push to ensure it is wrapped securely and is stable.

Continue wrapping if needed.